





1/19



2/19




Figure 1E




Figure 1F

3/19

16 ↗

↗ 16





Figure 2A

Figure 2B



4/19

Fig. 3A




Fig. 3B





Fig. 3C



5119




figure 4




Fig. 5A




Fig. 9A)

7/19




Fig 5B




Figure 6

9119




Fig. 7




Figure 8A

11/19




Figure 8B






Figure 9B









FIG. 10D



Foot Stirrup
w/ Connecting Ring

Figure 11




FIG. 13A





FIG. 12



19/19




Figure 14